



Certificate of Registration

APIQR® REGISTRATION NUMBER

0274

This certifies that the quality management system of

**WENLEN S.A.
Estrada 180
Bella Vista, Buenos Aires
Argentina**

has been assessed by the American Petroleum Institute Quality Registrar (APIQR®) and found it to be in conformance with the following standard:

ISO 9001:2015

The scope of this registration and the approved quality management system applies to the

Design, Manufacture, Repair, Remanufacture and Service of Wellhead and Christmas Tree Equipment, Pipeline Valves, Drill Through Equipment and Machined Parts; Hydraulic and Mechanical Assembly

APIQR® approves the organization's justification for excluding:

No Exclusions Identified as Applicable

Effective Date: MARCH 31, 2023
Expiration Date: MARCH 31, 2026
Registered Since: DECEMBER 3, 2001

Anchal Liddar

*Senior Vice President of
Global Industry Services*

Accredited by Member of
the International
Accreditation Forum
Multilateral Recognition
Arrangement for Quality
Management Systems



This certificate is valid for the period specified herein. The registered organization must continually meet all requirements of APIQR's Registration Program and the requirements of the Registration Agreement. Registration is maintained and regularly monitored through annual full system audits. Further clarifications regarding the scope of this certificate and the applicability of ISO 9001 standard requirements may be obtained by consulting the registered organization. This certificate has been issued from APIQR offices located at 200 Massachusetts Avenue, NW Suite 1100, Washington, DC 20001-5571, U.S.A., it is the property of APIQR, and must be returned upon request. To verify the authenticity of this certificate, go to www.api.org/compositelist.



2021-129 | 08.21 | PDF



Appendix to Certificate

WENLEN S.A.

This Appendix refers to **APIQR Registration No. ISO-0274**

Additional Locations included in this Certification are listed below.

Location	Activities
Jujuy 1100 Bella Vista Buenos Aries Argentina	Assembly, Repair, Remanufacture and Service, Hydraulic Testing and Quality Control of Gate and Ball Valves; Assembly and Quality Control of Actuators



American Petroleum Institute Quality Registrar
200 Massachusetts Avenue, NW
Suite 1100
Washington, DC 20001-5571
USA
www.api.org

